HISTORY KEPT YES ☐ NO ⊠	ILLINOIS HIGHWAY INFORMATION SYSTEM STRUCTURE INFORMATION AND PROCEDURE MANUAL					
NBIS REQUIRED YES ☐ NO ☑	ITEM NAME MAINTENANCE TEAM SECTION AND SUBSECTION - UNDER		ITEM NO. PAGE EFF. DATE	501&501A 1 of 1 07/01/02		
	ISIS	MMIS				
RESPONSIBLE FOR UPDATE	N/A	District	Maintenance	/Operations		
STRUCTURES	N/A	State				
UPDATE SCREENS	N/A	(6) Inve	entory			
INQUIRY SCREENS	(9) MMIS Inventory	(8) Inve	ntory			

DESCRIPTION AND PURPOSE OF ITEM

This item records the Team Section and Subsection information for a structure that is maintained by two Team Sections. Specifically, this item is used to identify the Team Section and Subsection in which the lower part of the structure is located.

CODE AND SCREEN ENTRY INSTRUCTIONS

Each item is a three-digit alphanumeric field.

Enter the Team Section and Subsection in the appropriate fields.

Leave blank when a structure is maintained by only one Team Section.

EXAMPLE:

Case #1: Team Section E23 has structure 016-0083 located in Subsection 014 and maintains the superstructure of the bridge. Team Section 022 has structure 016-0083 located in

Subsection 908 and maintains the substructure of this bridge.

Code in MMIS as follows:

Case #:	Structure #:	MMIS Data Field Name:	Enter:	ISIS Item:
1	016-0083	OVER/ONLY TS-SS	E23 - 014	500 & 500A
1	016-0083	Under TS-SS	022 - 908	501 & 501A